

A red and white helicopter is shown in flight against a clear sky, positioned in the upper left quadrant of the page.A close-up photograph of a thick, braided steel cable. A red metal hook is attached to the cable, and another hook is visible further down. The cable has some markings on it, including "FILIT 25113".

Invito della Rega

Progetto Remove:


segnalateci cavi, funivie e fili a sbalzo in disuso!

A close-up of a yellow and black hazard marker, which is a triangular-shaped object used for marking dangerous areas or objects.

Filovie e cavi sono un grave pericolo per gli elicotteri, ma anche per alianti e parapendii. Danni causati da cavi e fili possono provocare la caduta d'un elicottero. La Rega e l'esercito invitano pertanto i proprietari di funivie e/o cavi e fili fuori uso di segnalarli alla **base Rega più vicina oppure al numero telefonico 1414**. Gli specialisti civili o dell'esercito provvederanno a smontare ed eliminare gli ostacoli aerei senza costi per il proprietario.

Ulteriori foglie sono disponibili presso:

Guardia aerea svizzera di soccorso (Rega), Rega Center, Comunicazione, Casella postale 1414, 8058 Zurigo aeroporto

A close-up photograph showing a damaged metal surface, likely part of an aircraft. There are several rivets visible, and a piece of metal is missing, revealing the underlying structure and some wires.